

Offers speed and safety.

Achieved the maximum machine speed at 7,000 rpm.

The machine runs fastest in the world a long distance, such as hemming bottoms of T-shirts and similar garments, thus increasing production.

New design that ensures safety for the operator

The driving parts conventionally located on the front of the arm have been totally removed. Your operators work feeling at ease with the resultant increase in production and quality.

W2600 Subclasses

Carre	Town of marshins	Madal	No. of	No. of	Needle	Max. machine	Barranto
Seam	Type of machine	Model	needles	threads	space (mm)	speed (rpm)	Remarks
	Versatile machine						
	Versatile machine for various applications, such as plain seaming, covering, hemming	W2664S-01	2.3	4.5	3.2,4.0,4.8 5.6,6.4	6,500 7,000	
	Binding tape						
78	For binding tape on leg openings of briefs, neck openings of T-shirts or underwear, etc.	W2664-02	2.3	4.5	3.2,4.0,4.8 5.6,6.4	6,500	
	Covering						
	For covering overlock seams on T-shirts or sweat shirts	W2664-03F W2664-03G	2.3	4.5	4.0,4.8,5.6 6.5	6 500	Flattening out overlock seams Folding over overlock seams
	Attaching lace/elastic lace						
00	For attaching lace and/or elastic lace to women's underwear and similar garments	W2664-05	2.3	4.5	3.2,4.0,5.6 6.4	6,000	With fabric trimmer device
	Hemming						
66	For hemming flat and tubular goods, such as T-shirts, polo shirts and similar garments	W2664-08 W2664S-08	2.3	4.5	4.0,4.8,5.6,6.4	6,500 7,000	
		W2664-35			4.8,5.6,6.4	6,000	With fabric trimmer device
	Attaching flat elastic						
13 (4	For attaching flat elastic to tubular goods, such as the waists of briefs, etc.	W2664H-33	3	5	5.6,6.4		With fabric trimmer device, rear puller device
	Inserting elastic						
6 6	For inserting elastic into tubular goods, such as sweat pants, nightwear, etc.	W2664-34	2.3	4.5	4.8,5.6,6.4	6,000	

The maximum machine speed in this table is a value for reference with a standard stroke of the needle bar. Detailed adjustments may be required according to the sewing conditions.



Specifications

No. of needles
 No. of threads
 Needle space (mm)
 2 ~ 3 needles
 3 ~ 5 threads
 2-needle machines

(3.2, 4.0, 4.8, 5.6, 6.4)*
3-needle machines
(5.6, 6.4)

• Main feed dog's movement amount (mm)

Max. 4.5

● **Differential feed ratio** 1:0.6 - 1:1.1/1:0.9 - 1:1.8

◆ Presser foot lift (mm) Max. 7.0**
 ◆ Machine speed (rpm) Max. 7,000**

*Remove the middle needle from a 3-needle machine, if you use the machine as a 2-needle machine with a needle space of 5.6mm and 6.4mm.

**Depends on sewing conditions.







PEGASUS SEWING MACHINE MFG.CO.,LTD.

5-7-2,Sagisu,Fukushima-ku,Osaka 553-0002,Japan Phone:81-6-6458-4739 Telefax:81-6-6454-8785 http://www.pegasus.co.jp